

**'68** **Dealer
Service
Information
Bulletin****Attention: Service Manager****Subject: PARKING AND TURN SIGNAL LAMP ASSEMBLY CHANGED**

A new type park and turn signal lamp assembly is now being used in production and will also be used as the service replacement.

The early type lamp assembly can be identified as having two lamp sockets. The latest type lamp assembly has only one lamp socket.

Service front end lamp harnesses have provision for attachment to the early type (two lamp sockets) lamp assembly. When using this harness with the new type (single socket) lamp assembly, cut off the unused brown wire (with single connector) flush to the harness and tape over the exposed wire end completely.

SERVICE DEPARTMENT
PONTIAC MOTOR DIVISION
GENERAL MOTORS CORPORATION