


To fix the tabs mismatch... modifies the original bezel...NOT COOL!



line up this slot with this lamp tab to level the beam in the bezel. (so the lamp is horizontal in the seat) not exact, but close. at least one less cut to make.

need to cut a slot here for this tab

need to cut a slot here for this tab